

RFQ290819-3

29 August 2019

Wartsila
48 Huntingwood Drive,
Huntingwood NSW 2148

Attn: Stuart Air

Dear Stuart

RE: IN SERVICE SUPPORT – RFQ FOR REPAIR OF MHC ITEMS

Thales Australia, through its In-Service Support Contract for the HUON Class Minehunters, is dispatching to your attention the above equipment.

Each item is unserviceable with the cause being as per the attached sheet(s).

Kindly arrange for a quotation for the item(s) to be repaired & refurbished to as close to an “as new” condition as practical. *The quotation is to include any work required to ensure long term preservation of each item is possible e.g. removal of corrosion, painting etc.* A service report will be required with each item if the quote is approved.

The repair agency is required to contact Thales if they are not able to maintain the existing item configuration. Equipment that is returned for repair or refurbishment after being in-service must be maintained by the use of consumable spare parts identical to those originally installed. If an item requires repair or refurbishment by means other than the use of such consumables (eg welding, bushing, metal spray, use of different materials or parts), this requires the approval of Thales Australia.

Your earliest advice on the expected lead-time for the return of each item would be appreciated.

Please refer to Thales repair reference number(s) in all correspondence.

Ready for dispatch via TNT Express con note 284901455.

Should you wish to discuss any aspect of this request, please contact myself on

Phone	+61 2 4924 5011	Fax	+61 2 4924 5007
Mobile	+61 (0) 422 055 727	E-mail	steve.dorse@thalesgroup.com.au

Yours sincerely,



S Dorse
Repairs Coordinator
Minehunter ISS Newcastle
Thales Maritime Precinct

Repair Ref #	Part Number	Qty	Description	Vendor Part No.	Serial No.	Ship rec'd from	Fault
R23566	C16431-R	1	PUMP,DG SEA WATER	1Q 611428LA		Yarra	Mechanical seal failed, leaking seawater. Requires repair.